Work Order ID 56972

Tuesday, March 16, 2010 9:16:36 AM



Page 1

Item ID:

D4035-045

Accept



Setup Start

Stop



Revision ID:

Item Name:

Lid Rib Assembly, Fwd (Light)

Start Date:

3/16/2010

Start Oty: 4.00

Reg'd Oty: 4.00



Cust Item ID:

Customer:

Reference:

Approvals:

Required Date: 3/23/2010

Process Plan: MG

Date: \0-3-16 Tooling:

Date:

Run Start



QC:

Date: ____

SPC (Y/N):

Date:

Stop

Sequence ID/ Work Center ID

Operation Description

Set Up/ **Run Hours** Draw Number

Draw Rev.

Plan

Code

Accept Qty

Reject **Qty**

Reject Number

Insp. Stamp

Draw Nbr

Revision Nbr

D4035

Α

Weld per dwg A/R Aluminum rod Batch:

0.00



Large Fab Large Fab

100

Memo

0.00

/1- Cut D4035-1 as per dwg D4035

2- Drill holes as per dwg D4035 using DT9562

M112860

-3- remove identification marks and deburr

4- Weld bushing in rib as per dwg D4035



110

QC9- Inspect visual per QSI004- Fusion Welds

0.00



OC

Memo

0.00

BE10-03-29

Quality Control

Dart Aerospace I	Lta
------------------	-----

W/O:			W	ORK ORDER CHANG	ES			
DATE	STEP	PRO	OCEDURE CHA	ANGE	By Date Qty			Approval QC Inspector
Part No	:	PAR #:	Fault Cate	egory:	_ NCR: Yes	No DQA:	Date: _	
	R	esolution:	Disposition	on:	_ QA: N/C Cld	osed:	Date: _	
NCR:			WORK ORD	ER NON-CONFORMA	NCE (NCR)		
DATE	STEP	Description of NC Section A	Initial Chief Eng	Corrective Action Section Action Description Chief Eng	on B Sign & Date	Verification Section C	Approval Chief Eng	Approval QC Inspector
· · · · · · · · · · · · · · · · · · ·								
	ļ	·						

Page 2

Tuesday, March 16, 2010 9:16:37 AM

Item ID:

D4035-045

Accept

Setup Start

Revision ID:

Item Name:

Lid Rib Assembly, Fwd (Light)

Start Date:

Required Date: 3/23/2010

3/16/2010

Start Qty: 4.00

Req'd Qty: 4.00



Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date:

Run Start

QC: ____ Date:

Memo

Memo

SPC (Y/N):

Set Up/

Run Hours

Date:

Stop

Stop

Sequence ID/ **Work Center ID**

120

Quality Control

Operation Description

QC5- Inspect part completeness to step on W/O

Draw Number

Draw Plan Rev. Code

Accept Qty

Reject Reject Qty

Number Stamp

130

Packaging Packaging

Identify as per dwg & Stock Location:

0.00

0.00

140

Quality Control

QC

QC21- Final Inspection - Work Order Release

0.00

Memo

0.00

10/03/3198 N 10-3-31

Dart Aerospace L	∟td
------------------	-----

W/O:		WORK ORDER CHANGES									
DATE	STEP	PRO	OCEDURE CH	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
				· b							
Part No	:	PAR #:	Fault Cat	egory:	NCR: Yes	No DQA:		Date: _	····		
	R	esolution:	Dispositi	on:	QA: N/C C	losed:		_ Date:	•		
NCR:	,	•	WORK ORD	DER NON-CONFORM	ANCE (NC	R)					
DATE	STEP	Description of NC Section A	Initial	Corrective Action Sec Action Description	ction B	Verifica		Approval	Approval		
· · ·		SECTION A	Chief Eng	Chief Eng	Date		10	Chief Eng	QC Inspector		
*											
									,		

Picklist Print

Tuesday, March 16, 2010 9:16:36 AM

Work Order ID: 56972

D4035-045

Parent Item Name:

Lid Rib Assembly, Fwd (Light)

Comments:

Parent Item:

IPP RevA: new issue DD 10.01.25 verified by:EC

Purchased

per dwg revA 10.03.15 verified by:EC

IPP Rev:B as

Start Date: 3/16/2010

Start Qty: 4.00

Required Date: 3/23/2010

Required Qty: 4.00

Component Item ID/

M6061T6TS0.750W.06

Item Name D2953-175

Replacement Mfg/ Item ID

Purch Manufactured Bin Primary Location Item No

No

Last Location

Route Seq ID 100

Unit of Measure Hand Each

Qty on 2.0000

Loc Code

B56985

Loc Code

Remaining Qty To Pick 4.0000

Qty Issued Date Issued

Status

Page 1

Spacer

Location

Main Warehouse

ST

Warehouse

22096

2 100

Loc Qty


2

270.4300 7.8947


6061-T6 SQ Tube .75 x .75 x .062W

Warehouse	Loc Oty
Location	
Main Warehouse	
MAT	270.43
103069	147.94
104422	69.75
16441	18.74
9671	34


W/O:			W	ORK ORDER CHANG	iES				
DATE	STEP	PR	OCEDURE CHA	NGE	By Date Qty			Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	•	PAR #:	Fault Cate	gory:	_ NCR: Yes	No DQ	A:	_ Date: _	
	Res	solution:	Dispositio	n:	_ QA: N/C (Closed:		Date: _	
NCR:			WORK ORD	ER NON-CONFORM	ANCE (NC	R)			
DATE	STEP	Description of NC Section A	Initial	Corrective Action Sect Action Description	ion B	ign & Verification Section C		Approval	Approval
		Section A	Chief Eng	Chief Eng	Date		ion C	Chief Eng	QC Inspector
									
	,								




W/O:			WC	ORK ORDER CHANG	ES		<u>.</u>		
DATE	STEP	PR	OCEDURE CHA	·	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			. <u>.</u>						
	·								
Part No	:	PAR #:	Fault Cate	gory:	NCB: Ves	No DO	Δ.	Date	
		solution:							
NCR:				ER NON-CONFORM					· · · · · · · · · · · · · · · · · · ·
DATE	STEP	Description of NC			ion B	Verifi	cation	Approval	Approval QC Inspector
		STEP Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date	Sect		Chief Eng	
			1		i	- 1			ľ



									
W/O:			WC	ORK ORDER CHANGE	S				
DATE	STEP	PROCEDURE CHANGE				Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC inspector
Part No	·	PAR #:	Fault Cate	gory:	NCR: Yes	No DQ	A:	_ Date: _	
	Re	esolution:	Dispositio	n:	QA: N/C Cld	osed:		Date: _	
NCR:		•	WORK ORD	ER NON-CONFORMA	NCE (NCR)			
DATE	STEP	Description of NC		Corrective Action Section B Initial Action Description Sign &			Verification		Approval
		Section A	Initial Chief Eng	Action Description Chief Eng	Date	Secti	on C	Chief Eng	QC Inspector
								•	
							·		




W/O:			WC	RK ORDER CHANG	iES				
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			-			150 64 100			
			1.781						
Part No	•	PAR #:	Fault Cate	gory:	NCR: Yes	No DQ	1 A:	Date:	
		esolution:							
NCR:			WORK ORDI	ER NON-CONFORMA	ANCE (NCR	1)			
DATE	STED	Description of NC	cription of NC Corrective Action			Verific	rification Approval	Approval	Approval
	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section		Chief Eng	QC Inspector
	1 1		1 1		- 1				ŀ



Dart Aerospace	Ltd
----------------	-----

	•									
W/O:			WC	RK ORDER CHANG	GES					
DATE	STEP	PR	OCEDURE CHAI	NGE	By Date C			Qty Approval Chief Eng / Prod Mgr QC Inspec		
			. '							
Part No		PAR #:	Fault Cate	jory:	NCR: Ye	es No	DQA:	Date: _	<u> </u>	
		solution:								
NCR:			WORK ORDE	R NON-CONFORM	ANCE (N	CR)	<u> </u>		*-	
DATE STI	STED	Description of NC	Corrective Action Section B			Veritication		Approval	Approval	
	SIEF	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Section C		Chief Eng	QC Inspector	
				. •						



Da	rt A	\ero	Sp	ac	e L	.td
----	------	------	----	----	-----	-----

W/O:		WORK ORDER CHANGES										
DATE	DATE STEP P			OCEDURE CHANGE			Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
						i						
Part No:		PAR #:	•	NCR: Yes No DQA:				Date: _				
	Re	esolution:	Disposition:			QA: N/C Closed:			Date: _			
NCR:		•	WORK OR	DER NON-CONFORM	ANCE	(NCR)					
DATE	STEP	Description of NC Section A	Corrective Action Section				Verifi	cation	Approval	Approval		
			Initial Chief Eng	Action Description Chief Eng		Sign & Date		ion C	Chief Eng	QC Inspector		
				÷								
									:			
									•			
NOTE: D		1 . 11								l		